




Turbo Coolant Line Kit

AFTERMARKET EXCLUSIVE | **MAKE A BETTER REPAIR**



926-187

2011-2016 Ford F150, 2015-17 Lincoln Navigator, 2015-2021 Ford Transit 3.5L

PROBLEM:

The turbocharger coolant line on certain Ford and Lincoln vehicles often rusts and leaks at the junction point where it meets the quick disconnect fittings. The resulting coolant loss can lead to engine damage. Replacing it with an OEM coolant line could mean the same issue again in the future, a costly proposition with the labor guide calling for over nine hours to replace these parts.

FIX:

This Dorman OE FIX turbocharger coolant line replaces the OEM regular steel line with a stainless steel line for a more durable replacement that helps prevent future leaks. In addition, this is a complete kit to service the turbo coolant lines, including the supply line, return line, connectors and turbo mounting gasket.



CCV Diaphragm Repair Kit

AFTERMARKET EXCLUSIVE | **REPLACE JUST THE DIAPHRAGM, NOT THE ENTIRE ASSEMBLY**

NO NEED TO REPLACE ENTIRE CRANKCASE VENT OIL SEPARATOR ASSEMBLY **JUST TO FIX A FAILED DIAPHRAGM.**



918-359

Ford Super Duty 2019-11 6.7L Diesel

PROBLEM:

The diesel engine on certain Ford Super Duty trucks has a large and complex air separator box assembly on the engine that filters crankcase blowby gasses before they are re-introduced back into the engine intake. On this type of engine system, the PCV valve diaphragm becomes clogged with oil and carbon deposits, leading the air separator assembly to fail. This causes excessive crankcase pressure, resulting in oil leaks, high idle and a decrease in engine performance.


FIX:

This Dorman OE FIX PCV valve diaphragm allows the replacement of just the failed diaphragm instead of the whole separator assembly to reduce cost and downtime of the truck.



Auxiliary Air Conditioning & Heater Line Assembly

AFTERMARKET EXCLUSIVE | **SAVE TIME AND HASSLE**



926-866

Cadillac Escalade 2014-07, Chevrolet Tahoe 2014-07, GMC Yukon 2014-07

PROBLEM:

Routing a one-piece rear A/C line through certain GM SUVs can be a frustrating and time-consuming job.

FIX:

This Dorman OE FIX multi-piece kit simplifies the installation of rear A/C lines. Each section is engineered to be joined together with a threaded fitting for a leak-free repair.

Trailer Brake Control Switch

AFTERMARKET EXCLUSIVE

**RELIABLE OE REPLACEMENT OR PERFECT
FOR ADDING TRAILER BRAKES**



601-235

Dodge 2021-19, Ram 2021-13

- Helps enable the addition of trailer brakes, or is a reliable replacement for an original switch that has failed due to electrical malfunction
- Made from quality materials and components to ensure reliable performance and a long service life

Windshield A-Pillar Moldings (Black)

AFTERMARKET EXCLUSIVES

RESTORES PILLAR APPEARANCE



926-289 (Left) | 926-290 (Right)


Ford Flex 2019-11

- Restores like-new appearance to the windshield pillars when the originals have become deformed or detached
- Direct replacements that match the fit and appearance of the originals and require no special tools to install

Battery Circuit Fuse

AFTERMARKET EXCLUSIVE

RELIABLE DIRECT REPLACEMENT



956-356

Ram 2019-13

- Reliable replacement for an original fuse that is missing or has failed

Shock Tower Patch Panel (Rear Left)

AFTERMARKET EXCLUSIVE | **MAKE A PERMANENT FIX**



999-987

Ford Escape 2012-01, Mazda Tribute 2011-08,
Mazda Tribute 2006-01, Mercury Mariner 2011-05

- Welds into place and matches the fit and appearance of the original shock absorber mount
- Allows a permanent fix that helps to ensure the structural integrity of the body and shock mount and avoid a failed state inspection
- Made of rugged stamped steel, with a corrosion-resistant E-coat for a reliable repair

Rear Differential Actuator Motor

AFTERMARKET EXCLUSIVE

MADE TO EXACTING SPECIFICATIONS



699-996


Dodge Durango 2021-18, Jeep Grand Cherokee 2021-14

- Designed, manufactured and tested to strict specifications for reliable service
- Restores the correct distribution of power to the rear differential on specified vehicles

Smart Data Link Module

AFTERMARKET EXCLUSIVE

RIGOROUSLY TESTED FOR RELIABILITY



601-620

Ford 2021-15, Lincoln 2021-16

- This OBD-II data link module matches the function of an original module that has failed due to electrical malfunction or data corruption
- Engineered and tested to restore communications between the controller area network bus and devices and tools that utilize the onboard diagnostic port